



# WESTERN STATE HOSPITAL HAZARDOUS MATERIALS SURVEY

## LAB ANALYSIS BUILDING #115

# SanAir Technologies Laboratory

## Analysis Report

prepared for

**El Group, Inc Roanoke Office**

Report Date: 9/10/2013  
Project Name: City Of Staunton  
Project #: IHRO130196.00  
SanAir ID#: 13021161



**804.897.1177**

**www.sanair.com**



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

EI Group, Inc Roanoke Office  
15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

September 10, 2013

SanAir ID # 13021161  
Project Name: City Of Staunton  
Project Number: IHRO130196.00

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 20 sample(s) were received on Tuesday, September 10, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 115-1, 115-2, 115-3, 115-4, 115-5, 115-6, 115-7, 115-8, 115-9, 115-10, 115-11, 115-12, 115-13, 115-14, 115-15, 115-16, 115-17, 115-18, 115-19, 115-20.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino  
Asbestos & Materials Laboratory Manager  
SanAir Technologies Laboratory

Final Report Includes:  
- Cover Letter  
- Analysis Pages  
- Disclaimers and Additional Information

sample conditions:  
20 sample(s) in Good condition



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

**13021161**

FINAL REPORT

**Name:** El Group, Inc Roanoke Office  
**Address:** 15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

**Project Number:** IHRO130196.00  
**P.O. Number:**  
**Project Name:** City Of Staunton

**Collected Date:** 9/9/2013  
**Received Date:** 9/10/2013 9:30:00 AM  
**Report Date:** 9/10/2013 6:02:08 PM  
**Analyst:** Tallert, Jonathan G.

### Asbestos Bulk PLM EPA 600/R-93/116

| SanAir ID / Description            | Stereoscopic Appearance              | % Fibrous                      | Components    |  | Asbestos Fibers |
|------------------------------------|--------------------------------------|--------------------------------|---------------|--|-----------------|
|                                    |                                      |                                | % Non-Fibrous |  |                 |
| 115-1 / 13021161-001<br>Floor Tile | Beige<br>Non-Fibrous<br>Homogeneous  |                                | 100% Other    |  | None Detected   |
| 115-1 / 13021161-001<br>Mastic     | Yellow<br>Non-Fibrous<br>Homogeneous |                                | 100% Other    |  | None Detected   |
| 115-2 / 13021161-002<br>Floor Tile | Beige<br>Non-Fibrous<br>Homogeneous  |                                | 100% Other    |  | None Detected   |
| 115-2 / 13021161-002<br>Mastic     | Yellow<br>Non-Fibrous<br>Homogeneous |                                | 100% Other    |  | None Detected   |
| 115-3 / 13021161-003<br>Plaster    | Grey<br>Non-Fibrous<br>Homogeneous   |                                | 100% Other    |  | None Detected   |
| 115-3 / 13021161-003<br>Skim Coat  | White<br>Non-Fibrous<br>Homogeneous  |                                | 100% Other    |  | None Detected   |
| 115-4 / 13021161-004<br>Plaster    | Grey<br>Non-Fibrous<br>Homogeneous   |                                | 100% Other    |  | None Detected   |
| 115-4 / 13021161-004<br>Skim Coat  | White<br>Non-Fibrous<br>Homogeneous  |                                | 100% Other    |  | None Detected   |
| 115-5 / 13021161-005               | White<br>Fibrous<br>Homogeneous      | 40% Cellulose<br>40% Min. Wool | 20% Other     |  | None Detected   |

#### Certification

Signature:   
Date: 9/10/2013

Reviewed:   
Date: 9/10/2013

Page 1 of 4



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

**13021161**

FINAL REPORT

**Name:** El Group, Inc Roanoke Office  
**Address:** 15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

**Project Number:** IHRO130196.00  
**P.O. Number:**  
**Project Name:** City Of Staunton

**Collected Date:** 9/9/2013  
**Received Date:** 9/10/2013 9:30:00 AM  
**Report Date:** 9/10/2013 6:02:08 PM  
**Analyst:** Tallert, Jonathan G.

### Asbestos Bulk PLM EPA 600/R-93/116

| SanAir ID / Description | Stereoscopic Appearance         | Components                     |               | Asbestos Fibers |
|-------------------------|---------------------------------|--------------------------------|---------------|-----------------|
|                         |                                 | % Fibrous                      | % Non-Fibrous |                 |
| 115-6 / 13021161-006    | White<br>Fibrous<br>Homogeneous | 40% Cellulose<br>40% Min. Wool | 20% Other     | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|-------------------------|-------------------------------------|------------|---------------|-----------------|
|                         |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-7 / 13021161-007    | White<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|-------------------------|-------------------------------------|------------|---------------|-----------------|
|                         |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-8 / 13021161-008    | White<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance           | Components |               | Asbestos Fibers |
|-------------------------|-----------------------------------|------------|---------------|-----------------|
|                         |                                   | % Fibrous  | % Non-Fibrous |                 |
| 115-9 / 13021161-009    | Red<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance           | Components |               | Asbestos Fibers |
|-------------------------|-----------------------------------|------------|---------------|-----------------|
|                         |                                   | % Fibrous  | % Non-Fibrous |                 |
| 115-10 / 13021161-010   | Red<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

| SanAir ID / Description            | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|------------------------------------|-------------------------------------|------------|---------------|-----------------|
|                                    |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-11 / 13021161-011<br>Cove Base | Black<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |
| 115-11 / 13021161-011<br>Mastic    | Brown<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

### Certification

Signature:

Date: 9/10/2013

Reviewed:

Date: 9/10/2013

Page 2 of 4



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

**13021161**

FINAL REPORT

**Name:** El Group, Inc Roanoke Office  
**Address:** 15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

**Project Number:** IHRO130196.00  
**P.O. Number:**  
**Project Name:** City Of Staunton

**Collected Date:** 9/9/2013  
**Received Date:** 9/10/2013 9:30:00 AM  
**Report Date:** 9/10/2013 6:02:08 PM  
**Analyst:** Tallert, Jonathan G.

### Asbestos Bulk PLM EPA 600/R-93/116

| SanAir ID / Description            | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|------------------------------------|-------------------------------------|------------|---------------|-----------------|
|                                    |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-12 / 13021161-012<br>Cove Base | Black<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |
| 115-12 / 13021161-012<br>Mastic    | Brown<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

| SanAir ID / Description             | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|-------------------------------------|-------------------------------------|------------|---------------|-----------------|
|                                     |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-13 / 13021161-013<br>Floor Tile | Beige<br>Non-Fibrous<br>Homogeneous |            | 97% Other     | 3% Chrysotile   |
| 115-13 / 13021161-013<br>Mastic     | Black<br>Non-Fibrous<br>Homogeneous |            | 95% Other     | 5% Chrysotile   |

| SanAir ID / Description             | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|-------------------------------------|-------------------------------------|------------|---------------|-----------------|
|                                     |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-14 / 13021161-014<br>Floor Tile | Beige<br>Non-Fibrous<br>Homogeneous |            | 97% Other     | 3% Chrysotile   |
| 115-14 / 13021161-014<br>Mastic     | Black<br>Non-Fibrous<br>Homogeneous |            | 95% Other     | 5% Chrysotile   |

| SanAir ID / Description                 | Stereoscopic Appearance             | Components    |               | Asbestos Fibers |
|-----------------------------------------|-------------------------------------|---------------|---------------|-----------------|
|                                         |                                     | % Fibrous     | % Non-Fibrous |                 |
| 115-15 / 13021161-015<br>Drywall        | White<br>Non-Fibrous<br>Homogeneous | 10% Cellulose | 90% Other     | None Detected   |
| 115-15 / 13021161-015<br>Joint Compound | White<br>Non-Fibrous<br>Homogeneous |               | 100% Other    | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance             | Components    |               | Asbestos Fibers |
|-------------------------|-------------------------------------|---------------|---------------|-----------------|
|                         |                                     | % Fibrous     | % Non-Fibrous |                 |
| 115-16 / 13021161-016   | White<br>Non-Fibrous<br>Homogeneous | 10% Cellulose | 90% Other     | None Detected   |

#### Certification

Signature:   
Date: 9/10/2013

Reviewed:   
Date: 9/10/2013

Page 3 of 4



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

**13021161**

FINAL REPORT

**Name:** El Group, Inc Roanoke Office  
**Address:** 15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

**Project Number:** IHRO130196.00  
**P.O. Number:**  
**Project Name:** City Of Staunton

**Collected Date:** 9/9/2013  
**Received Date:** 9/10/2013 9:30:00 AM  
**Report Date:** 9/10/2013 6:02:08 PM  
**Analyst:** Tallert, Jonathan G.

### Asbestos Bulk PLM EPA 600/R-93/116

| SanAir ID / Description | Stereoscopic Appearance             | % Fibrous | Components    |  | Asbestos Fibers |
|-------------------------|-------------------------------------|-----------|---------------|--|-----------------|
|                         |                                     |           | % Non-Fibrous |  |                 |
| 115-17 / 13021161-017   | White<br>Non-Fibrous<br>Homogeneous |           | 100% Other    |  | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance             | % Fibrous | Components    |  | Asbestos Fibers |
|-------------------------|-------------------------------------|-----------|---------------|--|-----------------|
|                         |                                     |           | % Non-Fibrous |  |                 |
| 115-18 / 13021161-018   | White<br>Non-Fibrous<br>Homogeneous |           | 100% Other    |  | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance            | % Fibrous | Components    |  | Asbestos Fibers |
|-------------------------|------------------------------------|-----------|---------------|--|-----------------|
|                         |                                    |           | % Non-Fibrous |  |                 |
| 115-19 / 13021161-019   | Grey<br>Non-Fibrous<br>Homogeneous |           | 100% Other    |  | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance            | % Fibrous | Components    |  | Asbestos Fibers |
|-------------------------|------------------------------------|-----------|---------------|--|-----------------|
|                         |                                    |           | % Non-Fibrous |  |                 |
| 115-20 / 13021161-020   | Grey<br>Non-Fibrous<br>Homogeneous |           | 100% Other    |  | None Detected   |

#### Certification

Signature:

Date: 9/10/2013

Reviewed:

Date: 9/10/2013

Page 4 of 4

### Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

SanAir ID Number  
13021161

|                                     |                                       |                                 |                                  |
|-------------------------------------|---------------------------------------|---------------------------------|----------------------------------|
| Company: <u>EJ Group, Inc.</u>      |                                       | Project #: <u>IH80130196.00</u> | Collect by: <u>Stephen Clark</u> |
| Address: <u>205 Walnut Hills Rd</u> | Project Name: <u>City of Staunton</u> |                                 | Phone #:                         |
| City, St., Zip: <u>Staunton, VA</u> | Date Collected:                       |                                 | Fax #:                           |
| State of Collection: <u>VA</u>      | Account#:                             | P.O. Number:                    | Email:                           |

| Bulk  |                                        |                                     | Air           |                       |                          | Soil/Vermiculite |                              |                          |
|-------|----------------------------------------|-------------------------------------|---------------|-----------------------|--------------------------|------------------|------------------------------|--------------------------|
| ABB   | PLM EPA 600/R-93/116                   | <input checked="" type="checkbox"/> | ABA           | PCM NIOSH 7400        | <input type="checkbox"/> | ABSE             | PLM EPA 600/R-93/116 (Qual.) | <input type="checkbox"/> |
|       | Positive Stop <input type="checkbox"/> |                                     | ABA-2         | OSHA w/ TWA*          | <input type="checkbox"/> | ABSP             | PLM CARB 435 (LOD <1%)       | <input type="checkbox"/> |
| ABEPA | PLM EPA 400 Point Count                | <input type="checkbox"/>            | ABTEM         | TEM AHERA             | <input type="checkbox"/> | ABSP1            | PLM CARB 435 (LOD 0.25%)     | <input type="checkbox"/> |
| ABB1K | PLM EPA 1000 Point Count               | <input type="checkbox"/>            | ABATN         | TEM NIOSH 7402        | <input type="checkbox"/> | ABSP2            | PLM CARB 435 (LOD 0.1%)      | <input type="checkbox"/> |
| ABBen | PLM EPA NOB                            | <input type="checkbox"/>            | ABT2          | TEM Level II          | <input type="checkbox"/> |                  |                              |                          |
| ABBCH | TEM Chatfield                          | <input type="checkbox"/>            |               |                       |                          |                  |                              |                          |
| ABBTM | TEM EPA NOB                            | <input type="checkbox"/>            |               |                       |                          |                  |                              |                          |
| Water |                                        |                                     | New York ELAP |                       |                          | Dust             |                              |                          |
|       |                                        |                                     | PLM NY        | PLM 600/M4/82/020     | <input type="checkbox"/> | ABWA             | TEM Wipe ASTM D-6480         | <input type="checkbox"/> |
|       |                                        |                                     | ABEPA2        | NY ELAP 198.1         | <input type="checkbox"/> | ABDMV            | TEM Microvac ASTM D-5755     | <input type="checkbox"/> |
|       |                                        |                                     | ABENY         | NY ELAP 198.6 PLM NOB | <input type="checkbox"/> |                  |                              |                          |
| ABHE  | EPA 100.2                              | <input type="checkbox"/>            | ABBNY         | NY ELAP 198.4 TEM NOB | <input type="checkbox"/> | Matrix           | Other                        |                          |

|                      |                                          |                                         |                                 |                                           |
|----------------------|------------------------------------------|-----------------------------------------|---------------------------------|-------------------------------------------|
| Turn Around<br>Times | 3 HR (4 HR TEM) <input type="checkbox"/> | 6 HR (8HR TEM) <input type="checkbox"/> | 12 HR <input type="checkbox"/>  | 24 HR <input checked="" type="checkbox"/> |
|                      | 2 Days <input type="checkbox"/>          | 3 Days <input type="checkbox"/>         | 4 Days <input type="checkbox"/> | 5 Days <input type="checkbox"/>           |

### Special Instructions

[illegible]

|                    |          |       |                    |             |         |
|--------------------|----------|-------|--------------------|-------------|---------|
| Relinquished by    | Date     | Time  | Received by        | Date        | Time    |
| <i>[Signature]</i> | 9/9/2013 | 17:00 | <i>[Signature]</i> | SEP 10 2013 | 9:30 AM |

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

# SanAir Technologies Laboratory

## Analysis Report

prepared for

**El Group, Inc Roanoke Office**

Report Date: 9/12/2013  
Project Name: City Of Staunton  
Project #: IHRO130196  
SanAir ID#: 13021269



**804.897.1177**

**www.sanair.com**



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

EI Group, Inc Roanoke Office  
15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

September 12, 2013

SanAir ID # 13021269  
Project Name: City Of Staunton  
Project Number: IHRO130196

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 1 sample(s) were received on Wednesday, September 11, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 115-21.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino  
Asbestos & Materials Laboratory Manager  
SanAir Technologies Laboratory

Final Report Includes:  
- Cover Letter  
- Analysis Pages  
- Disclaimers and Additional Information

sample conditions:  
1 sample(s) in Good condition



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

**13021269**

FINAL REPORT

**Name:** El Group, Inc Roanoke Office  
**Address:** 15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

**Project Number:** IHRO130196  
**P.O. Number:**  
**Project Name:** City Of Staunton

**Collected Date:** 9/10/2013  
**Received Date:** 9/11/2013 10:10:00 AM  
**Report Date:** 9/12/2013 10:59:57 AM  
**Analyst:** Sobrino, Sandra

### Asbestos Bulk PLM EPA 600/R-93/116

| SanAir ID / Description | Stereoscopic<br>Appearance         | Components |               | Asbestos<br>Fibers |
|-------------------------|------------------------------------|------------|---------------|--------------------|
|                         |                                    | % Fibrous  | % Non-Fibrous |                    |
| 115-21 / 13021269-001   | Grey<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected      |

#### Certification

Signature: *Sandra Sobrino*  
Date: 9/12/2013

Reviewed: *Sandra Sobrino*  
Date: 9/12/2013

Page 1 of 1

### Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983



# SanAir Technologies Laboratory

## Analysis Report

prepared for

**El Group, Inc Roanoke Office**

Report Date: 9/16/2013  
Project Name: City Of Staunton-  
Bldg115  
Project #: IHRO130196.00  
SanAir ID#: 13021565



Certification # 652931



License # LAB0166



**804.897.1177**

**www.sanair.com**



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

EI Group, Inc Roanoke Office  
15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

September 16, 2013

SanAir ID # 13021565  
Project Name: City Of Staunton-Bldg115  
Project Number: IHRO130196.00

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 2 sample(s) were received on Friday, September 13, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 115-22, 115-23.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino  
Asbestos & Materials Laboratory Manager  
SanAir Technologies Laboratory

Final Report Includes:  
- Cover Letter  
- Analysis Pages  
- Disclaimers and Additional Information

sample conditions:  
2 sample(s) in Good condition



## SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

**13021565**

FINAL REPORT

**Name:** El Group, Inc Roanoke Office  
**Address:** 15 Salem Ave SE  
Suite 301  
Roanoke, VA 24011

**Project Number:** IHRO130196.00  
**P.O. Number:**  
**Project Name:** City Of Staunton-Bldg115

**Collected Date:** 9/12/2013  
**Received Date:** 9/13/2013 10:20:00 AM  
**Report Date:** 9/16/2013 9:50:22 AM  
**Analyst:** Tallert, Jonathan G.

### Asbestos Bulk PLM EPA 600/R-93/116

| SanAir ID / Description | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|-------------------------|-------------------------------------|------------|---------------|-----------------|
|                         |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-22 / 13021565-001   | Black<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

| SanAir ID / Description | Stereoscopic Appearance             | Components |               | Asbestos Fibers |
|-------------------------|-------------------------------------|------------|---------------|-----------------|
|                         |                                     | % Fibrous  | % Non-Fibrous |                 |
| 115-23 / 13021565-002   | Black<br>Non-Fibrous<br>Homogeneous |            | 100% Other    | None Detected   |

#### Certification

Signature:   
Date: 9/16/2013

Reviewed:   
Date: 9/16/2013

Page 1 of 1

### Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

# SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139  
804-897-1177 / 888-895-1177 / Fax 804-897-0070  
www.sanair.com

## Asbestos Chain of Custody

SanAir ID Number

13021565

|                                          |                                                  |                                  |
|------------------------------------------|--------------------------------------------------|----------------------------------|
| Company: <u>EI Group - Staunton</u>      | Project #: <u>IR013019600</u>                    | Collect by: <u>Stephen Clark</u> |
| Address: <u>206 Walnut Hills Rd</u>      | Project Name: <u>City of Staunton - Bldg 115</u> | Phone #:                         |
| City, St., Zip: <u>Staunton, VA</u>      | Date Collected: <u>9/12/2013</u>                 | Fax #:                           |
| State of Collection: <u>VA</u> Account#: | P.O. Number:                                     | Email:                           |

| Bulk  |                                                          | Air           |                                                | Soil/Vermiculite |                                                       |
|-------|----------------------------------------------------------|---------------|------------------------------------------------|------------------|-------------------------------------------------------|
| ABB   | PLM EPA 600/R-93/116 <input checked="" type="checkbox"/> | ABA           | PCM NIOSH 7400 <input type="checkbox"/>        | ABSE             | PLM EPA 600/R-93/116 (Qual.) <input type="checkbox"/> |
|       | Positive Stop <input type="checkbox"/>                   | ABA-2         | OSHA w/ TWA* <input type="checkbox"/>          | ABSP             | PLM CARB 435 (LOD <1%) <input type="checkbox"/>       |
| ABEPA | PLM EPA 400 Point Count <input type="checkbox"/>         | ABTEM         | TEM AHERA <input type="checkbox"/>             | ABSP1            | PLM CARB 435 (LOD 0.25%) <input type="checkbox"/>     |
| ABBTK | PLM EPA 1000 Point Count <input type="checkbox"/>        | ABATN         | TEM NIOSH 7402 <input type="checkbox"/>        | ABSP2            | PLM CARB 435 (LOD 0.1%) <input type="checkbox"/>      |
| ABBEN | PLM EPA NOB <input type="checkbox"/>                     | ABT2          | TEM Level II <input type="checkbox"/>          |                  |                                                       |
| ABBCH | TEM Chatfield <input type="checkbox"/>                   |               |                                                |                  |                                                       |
| ABBTM | TEM EPA NOB <input type="checkbox"/>                     |               |                                                |                  |                                                       |
| Water |                                                          | New York ELAP |                                                | Dust             |                                                       |
| ABHE  | EPA 100.2 <input type="checkbox"/>                       | PLM NY        | PLM 600/M4/82/020 <input type="checkbox"/>     | ABWA             | TEM Wipe ASTM D-6480 <input type="checkbox"/>         |
|       |                                                          | ABEPA2        | NY ELAP 198.1 <input type="checkbox"/>         | ABDMV            | TEM Microvac ASTM D-5755 <input type="checkbox"/>     |
|       |                                                          | ABENY         | NY ELAP 198.6 PLM NOB <input type="checkbox"/> | Matrix           | Other <input type="checkbox"/>                        |
|       |                                                          | ABBNY         | NY ELAP 198.4 TEM NOB <input type="checkbox"/> |                  |                                                       |

| Turn Around Times | 3 HR (4 HR TEM) <input type="checkbox"/> | 6 HR (8HR TEM) <input type="checkbox"/> | 12 HR <input type="checkbox"/>  | 24 HR <input checked="" type="checkbox"/> |
|-------------------|------------------------------------------|-----------------------------------------|---------------------------------|-------------------------------------------|
|                   | 2 Days <input type="checkbox"/>          | 3 Days <input type="checkbox"/>         | 4 Days <input type="checkbox"/> | 5 Days <input type="checkbox"/>           |

### Special Instructions

| Sample # | Sample Identification/Location | Volume or Area | Sample Type | Flow Rate* | Time* Start - Stop |
|----------|--------------------------------|----------------|-------------|------------|--------------------|
| 115-22   |                                |                | ABB         |            |                    |
| 115-23   |                                |                | ABB         |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |
|          |                                |                |             |            |                    |

| Relinquished by    | Date           | Time         | Received by        | Date               | Time            |
|--------------------|----------------|--------------|--------------------|--------------------|-----------------|
| <u>[Signature]</u> | <u>9/12/13</u> | <u>17:00</u> | <u>[Signature]</u> | <u>SEP 13 2013</u> | <u>10:30 AM</u> |

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.