



WESTERN STATE HOSPITAL HAZARDOUS MATERIALS SURVEY

LAB ANALYSIS BUILDING #122

SanAir Technologies Laboratory

Analysis Report

prepared for

El Group, Inc Roanoke Office

Report Date: 9/5/2013
Project Name: Western State Bldg
122
Project #: 196
SanAir ID#: 13020622



804.897.1177

www.sanair.com



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

El Group, Inc Roanoke Office
15 Salem Ave SE
Suite 301
Roanoke, VA 24011

September 5, 2013

SanAir ID # 13020622
Project Name: Western State Bldg 122
Project Number: 196

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 39 sample(s) were received on Thursday, September 05, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 122-1, 122-2, 122-3, 122-4, 122-5, 122-6, 122-7, 122-8, 122-9, 122-10, 122-11, 122-12, 122-13, 122-14, 122-15, 122-16, 122-17, 122-18, 122-19, 122-20, 122-21, 122-22, 122-23, 122-24, 122-25, 122-26, 122-27, 122-28, 122-29, 122-30, 122-31, 122-32, 122-33, 122-34, 122-35, 122-36, 122-37, 122-38, 122-39.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:
- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:
39 sample(s) in Good condition



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020622

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Western State Bldg 122

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:12:05 PM
Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-1 / 13020622-001 Floor Tile	Tan Non-Fibrous Homogeneous		97% Other	3% Chrysotile
122-1 / 13020622-001 Mastic	Black Non-Fibrous Homogeneous		96% Other	4% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-2 / 13020622-002 Floor Tile	Tan Non-Fibrous Homogeneous		97% Other	3% Chrysotile
122-2 / 13020622-002 Mastic	Black Non-Fibrous Homogeneous		96% Other	4% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-3 / 13020622-003 Ceiling Tile	White Fibrous Homogeneous	55% Glass 30% Cellulose	15% Other	None Detected
122-3 / 13020622-003 Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-4 / 13020622-004 Ceiling Tile	White Fibrous Homogeneous	55% Glass 25% Cellulose	20% Other	None Detected
122-4 / 13020622-004 Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-5 / 13020622-005 Cove Base	Brown Non-Fibrous Homogeneous		100% Other	None Detected
122-5 / 13020622-005 Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 1 of 7



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020622

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Western State Bldg 122

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:12:05 PM
Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
122-6 / 13020622-006 Cove Base	Brown Non-Fibrous Homogeneous		100% Other	None Detected
122-6 / 13020622-006 Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
122-7 / 13020622-007	Black Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
122-8 / 13020622-008	Black Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
122-9 / 13020622-009 Plaster	Beige Non-Fibrous Homogeneous		100% Other	None Detected
122-9 / 13020622-009 Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
122-10 / 13020622-010 Plaster	Beige Non-Fibrous Homogeneous		100% Other	None Detected
122-10 / 13020622-010 Skim Coat	White Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 2 of 7



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020622

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Western State Bldg 122

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:12:05 PM
Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-11 / 13020622-011	Grey Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-12 / 13020622-012	Grey Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-13 / 13020622-013 Drywall	Off-White Non-Fibrous Homogeneous	2% Cellulose	98% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-14 / 13020622-014 Drywall	Off-White Non-Fibrous Homogeneous	2% Cellulose	98% Other	None Detected
122-14 / 13020622-014 Joint Compound	White Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-15 / 13020622-015 Floor Tile	Grey Non-Fibrous Homogeneous		100% Other	None Detected
122-15 / 13020622-015 Mastic	Black Non-Fibrous Homogeneous	2% Cellulose	98% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-16 / 13020622-016 Floor Tile	Grey Non-Fibrous Homogeneous		100% Other	None Detected
122-16 / 13020622-016 Mastic	Black Non-Fibrous Homogeneous	2% Cellulose	98% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 3 of 7



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020622

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Western State Bldg 122

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:12:05 PM
Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-17 / 13020622-017 Floor Tile	White Non-Fibrous Homogeneous		100% Other	None Detected
122-17 / 13020622-017 Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-18 / 13020622-018 Floor Tile	White Non-Fibrous Homogeneous		100% Other	None Detected
122-18 / 13020622-018 Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-19 / 13020622-019	White Fibrous Homogeneous	55% Cellulose 35% Glass	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-20 / 13020622-020	White Fibrous Homogeneous	55% Cellulose 35% Glass	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-21 / 13020622-021	White Fibrous Homogeneous	55% Cellulose 35% Glass	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-22 / 13020622-022	White Fibrous Homogeneous	55% Cellulose 35% Glass	10% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 4 of 7



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020622

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Western State Bldg 122

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:12:05 PM
Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-23 / 13020622-023	Grey Non-Fibrous Homogeneous	20% Glass < 1% Cellulose	80% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-24 / 13020622-024	Grey Non-Fibrous Homogeneous	20% Glass < 1% Cellulose	80% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-25 / 13020622-025	Grey Non-Fibrous Homogeneous	20% Glass < 1% Cellulose	80% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-26 / 13020622-026	White Fibrous Homogeneous	60% Cellulose 30% Glass	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-27 / 13020622-027	White Fibrous Homogeneous	60% Cellulose 30% Glass	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-28 / 13020622-028	Black Non-Fibrous Homogeneous	4% Glass	86% Other	10% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-29 / 13020622-029	Black Non-Fibrous Homogeneous	4% Glass	86% Other	10% Chrysotile

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 5 of 7



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020622

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Western State Bldg 122

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:12:05 PM
Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-30 / 13020622-030 Cove Base	Grey Non-Fibrous Homogeneous		100% Other	None Detected
122-30 / 13020622-030 Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-31 / 13020622-031 Cove Base	Grey Non-Fibrous Homogeneous		100% Other	None Detected
122-31 / 13020622-031 Mastic	Brown Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-32 / 13020622-032	White Fibrous Homogeneous	55% Cellulose 35% Glass	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-33 / 13020622-033	White Fibrous Homogeneous	55% Cellulose 35% Glass	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-34 / 13020622-034 Floor Tile	Various Non-Fibrous Homogeneous		100% Other	None Detected
122-34 / 13020622-034 Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 6 of 7



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020622

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Western State Bldg 122

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:12:05 PM
Analyst: Childress, Susan

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-35 / 13020622-035 Floor Tile	Various Non-Fibrous Homogeneous		100% Other	None Detected
122-35 / 13020622-035 Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-36 / 13020622-036 Stair Tread	Red Non-Fibrous Homogeneous		100% Other	None Detected
122-36 / 13020622-036 Mastic	Black Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-37 / 13020622-037 Stair Tread	Red Non-Fibrous Homogeneous		100% Other	None Detected
122-37 / 13020622-037 Mastic	Black Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-38 / 13020622-038 Floor Tile	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
122-38 / 13020622-038 Mastic	Black Non-Fibrous Homogeneous		97% Other	3% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-39 / 13020622-039 Floor Tile	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
122-39 / 13020622-039 Mastic	Black Non-Fibrous Homogeneous		97% Other	3% Chrysotile

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 7 of 7

Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

Asbestos Chain of Custody

SanAir ID Number

13020622

Company: <u>E-I</u>	Project #: <u>156</u>	Collect by:
Address:	Project Name: <u>Western State</u>	Phone #:
City, St., Zip:	Date Collected: <u>bls 122</u>	Fax #:
State of Collection:	Account#:	P.O. Number:
		Email:

Bulk		Air		Soil/Vermiculite	
ABB	PLM EPA 600/R-93/116 ☒	ABA	PCM NIOSH 7400 ☐	ABSE	PLM EPA 600/R-93/116 (Qual.) ☐
	Positive Stop ☐	ABA-2	OSHA w/ TWA* ☐	ABSP	PLM CARB 435 (LOD <1%) ☐
ABEPA	PLM EPA 400 Point Count ☐	ABTEM	TEM AHERA ☐	ABSP1	PLM CARB 435 (LOD 0.25%) ☐
ABB1K	PLM EPA 1000 Point Count ☐	ABATN	TEM NIOSH 7402 ☐	ABSP2	PLM CARB 435 (LOD 0.1%) ☐
ABBEN	PLM EPA NOB ☐	ABT2	TEM Level II ☐		
ABBCH	TEM Chatfield ☐				
ABBTM	TEM EPA NOB ☐				
		New York ELAP		Dust	
		PLM NY	PLM 600/M4/82/020 ☐	ABWA	TEM Wipe ASTM D-6480 ☐
		ABEPA2	NY ELAP 198.1 ☐	ABDMV	TEM Microvac ASTM D-5755 ☐
		ABENY	NY ELAP 198.6 PLM NOB ☐		
		ABBNY	NY ELAP 198.4 TEM NOB ☐		
				Matrix	Other ☐

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☐
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

Special Instructions

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
122-001	Tan 9x9 w/black mastic				
002	" " " "				
003	1x1 ct with mastic				
004	" " " "				
005	Brown CB with mastic				
006	" " " "				
007	Black window slate				
008	" " " "				
009	Plaster ceiling with Brown Backing				
010	" " " "				
011	Interior bldg Cavity				
012	" " " "				

Relinquished by	Date	Time	Received by	Date	Time
			<u>KE</u>	SEP 05 2013	10:50am

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

Page 1 of 4

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

SanAir ID Number

13020622

Company: <i>EF</i>		Project #: <i>196</i>	Collect by:
Address:		Project Name: <i>Western State</i>	Phone #:
City, St., Zip:		Date Collected: <i>Bids 122</i>	Fax #:
State of Collection:	Account#:	P.O. Number:	Email:

Bulk			Air			Soil/Vermiculite		
ABB	PLM EPA 600/R-93/116	☒	ABA	PCM NIOSH 7400	☐	ABSE	PLM EPA 600/R-93/116 (Qual.)	☐
	Positive Stop	☐	ABA-2	OSHA w/ TWA*	☐	ABSP	PLM CARB 435 (LOD <1%)	☐
ABEPA	PLM EPA 400 Point Count	☐	ABTEM	TEM AHERA	☐	ABSP1	PLM CARB 435 (LOD 0.25%)	☐
ABB1K	PLM EPA 1000 Point Count	☐	ABATN	TEM NIOSH 7402	☐	ABSP2	PLM CARB 435 (LOD 0.1%)	☐
ABBen	PLM EPA NOB	☐	ABT2	TEM Level II	☐			
ABBCH	TEM Chatfield	☐						
ABBTM	TEM EPA NOB	☐						
Water			New York ELAP			Dust		
			PLM NY	PLM 600/M4/82/020	☐	ABWA	TEM Wipe ASTM D-6480	☐
			ABEPA2	NY ELAP 198.1	☐	ABDMV	TEM Microvac ASTM D-5755	☐
			ABENY	NY ELAP 198.6 PLM NOB	☐			
ABHE	EPA 100.2	☐	ABBNY	NY ELAP 198.4 TEM NOB	☐	Matrix	Other	

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☐
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

Special Instructions

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
122-013	Drywall w/IC				
014	" "				
015	12X12 with mastic scrap				
016	" " " "				
017	12X12 white with mastic				
018	" " " "				
019	2x2 CT				
020	" "				
021	2x4 CT				
022	" "				
023	MJP				
024	" "				

Relinquished by	Date	Time	Received by	Date	Time
			<i>KF</i>	SEP 05 2013	1015am

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

Asbestos Chain of Custody

SanAir ID Number

13020622

Company: <u>ET</u>	Project #: <u>196</u>	Collect by:
Address:	Project Name: <u>Western STGTR</u>	Phone #:
City, St., Zip:	Date Collected: <u>Bldg 122</u>	Fax #:
State of Collection:	Account#:	P.O. Number:
		Email:

Bulk		Air		Soil/Vermiculite	
ABB	PLM EPA 600/R-93/116 ☒	ABA	PCM NIOSH 7400 ☐	ABSE	PLM EPA 600/R-93/116 (Qual.) ☐
	Positive Stop ☐	ABA-2	OSHA w/ TWA* ☐	ABSP	PLM CARB 435 (LOD <1%) ☐
ABEPA	PLM EPA 400 Point Count ☐	ABTEM	TEM AHERA ☐	ABSP1	PLM CARB 435 (LOD 0.25%) ☐
ABB1K	PLM EPA 1000 Point Count ☐	ABATN	TEM NIOSH 7402 ☐	ABSP2	PLM CARB 435 (LOD 0.1%) ☐
ABBN	PLM EPA NOB ☐	ABT2	TEM Level II ☐		
ABBCH	TEM Chatfield ☐				
ABBTM	TEM EPA NOB ☐				
		New York ELAP		Dust	
		PLM NY	PLM 600/M4/82/020 ☐	ABWA	TEM Wipe ASTM D-6480 ☐
		ABEPA2	NY ELAP 198.1 ☐	ABDMV	TEM Microvac ASTM D-5755 ☐
		ABENY	NY ELAP 198.6 PLM NOB ☐	Matrix	Other ☐
		ABBNY	NY ELAP 198.4 TEM NOB ☐		
Water					
ABHE	EPA 100.2 ☐				

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☐
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

Special Instructions

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
122-025	MTF				
026	Dry wall ceiling TC				
027	" "				
028	Black pipe mastic				
029	" "				
030	Gray concrete base w/mastic				
031	" "				
032	1x1 pin hole CT				
033	" "				
034	speckled gyp				
035	" "				
✓ 036	1" red stain wood				

Relinquished by	Date	Time	Received by	Date	Time
			<i>[Signature]</i>	SEP 05 2013	10:50 AM

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

Asbestos
Chain of Custody

SanAir ID Number

13020622

Company: <u>EI</u>		Project #: <u>196</u>	Collect by:
Address:		Project Name: <u>Western State</u>	Phone #:
City, St., Zip:		Date Collected: <u>Bldg 122</u>	Fax #:
State of Collection:	Account#:	P.O. Number:	Email:

Bulk		Air		Soil/Vermiculite	
ABB	PLM EPA 600/R-93/116 ☒	ABA	PCM NIOSH 7400 ☐	ABSE	PLM EPA 600/R-93/116 (Qual.) ☐
	Positive Stop ☐	ABA-2	OSHA w/ TWA* ☐	ABSP	PLM CARB 435 (LOD <1%) ☐
ABEPA	PLM EPA 400 Point Count ☐	ABTEM	TEM AHERA ☐	ABSP1	PLM CARB 435 (LOD 0.25%) ☐
ABB1K	PLM EPA 1000 Point Count ☐	ABATN	TEM NIOSH 7402 ☐	ABSP2	PLM CARB 435 (LOD 0.1%) ☐
ABBEN	PLM EPA NOB ☐	ABT2	TEM Level II ☐		
ABBCH	TEM Chatfield ☐				
ABBTM	TEM EPA NOB ☐				

Water		New York ELAP		Dust	
ABHE	EPA 100.2 ☐	PLM NY	PLM 600/M4/82/020 ☐	ABWA	TEM Wipe ASTM D-6480 ☐
		ABEPA2	NY ELAP 198.1 ☐	ABDMV	TEM Microvac ASTM D-5755 ☐
		ABENY	NY ELAP 198.6 PLM NOB ☐		
		ABBNY	NY ELAP 198.4 TEM NOB ☐	Matrix	Other ☐

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☐
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

Special Instructions

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
122-037	red stair 7 local				
038	12x12 yellow				
039	12x12 yellow				
040					

Relinquished by	Date	Time	Received by	Date	Time
			<i>KF</i>	SEP 05 2013	10:15 AM

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

Page 4 of 4

SanAir Technologies Laboratory

Analysis Report

prepared for

El Group, Inc Roanoke Office

Report Date: 9/10/2013
Project Name: Bldg 122-Ext
Project #: 196
SanAir ID#: 13020998



804.897.1177

www.sanair.com



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

EI Group, Inc Roanoke Office
15 Salem Ave SE
Suite 301
Roanoke, VA 24011

September 10, 2013

SanAir ID # 13020998
Project Name: Bldg 122-Ext
Project Number: 196

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 6 sample(s) were received on Monday, September 09, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 122-1EXT, 122-2EXT, 122-3EXT, 122-4EXT, 122-5EXT, 122-6EXT.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:
- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:
6 sample(s) in Good condition



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020998

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: 196
P.O. Number:
Project Name: Bldg 122-Ext

Collected Date: 9/6/2013
Received Date: 9/9/2013 9:55:00 AM
Report Date: 9/10/2013 10:07:36 AM
Analyst: Sobrino, Sandra

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
122-1EXT / 13020998-001	Grey Non-Fibrous Homogeneous		100%	Other	None Detected
122-2EXT / 13020998-002	Grey Non-Fibrous Homogeneous		100%	Other	None Detected
122-3EXT / 13020998-003	Grey Non-Fibrous Homogeneous		100%	Other	None Detected
122-4EXT / 13020998-004	Grey Non-Fibrous Homogeneous		100%	Other	None Detected
122-5EXT / 13020998-005	Grey Non-Fibrous Homogeneous		100%	Other	None Detected
122-6EXT / 13020998-006	Grey Non-Fibrous Homogeneous		100%	Other	None Detected

Certification

Signature: *Sandra Sobrino*
Date: 9/10/2013

Reviewed: *[Signature]*
Date: 9/10/2013

Page 1 of 1

Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

SanAir Technologies Laboratory, Inc.
1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

Asbestos
Chain of Custody

SanAir ID Number

13020998

Company: <u>ET</u>	Project #: <u>196</u>	Collect by: <u>V. L. ST</u>
Address:	Project Name: <u>Bldg 122-EXT</u>	Phone #:
City, St., Zip:	Date Collected: <u>9-6-13</u>	Fax #:
State of Collection:	Account#:	P.O. Number:
		Email:

Bulk		Air		Soil/Vermiculite	
ABB	PLM EPA 600/R-93/116 ☒	ABA	PCM NIOSH 7400 ☐	ABSE	PLM EPA 600/R-93/116 (Qual.) ☐
	Positive Stop ☐	ABA-2	OSHA w TWA* ☐	ABSP	PLM CARB 435 (LOD <1%) ☐
ABEPA	PLM EPA 400 Point Count ☐	ABTEM	TEM AHERA ☐	ABSP1	PLM CARB 435 (LOD 0.25%) ☐
ABB1K	PLM EPA 1000 Point Count ☐	ABATN	TEM NIOSH 7402 ☐	ABSP2	PLM CARB 435 (LOD 0.1%) ☐
ABBEN	PLM EPA NOB ☐	ABT2	TEM Level II ☐		
ABBCH	TEM Chatfield ☐				
ABBTM	TEM EPA NOB ☐				

Water		New York ELAP		Dust	
ABHE	EPA 100.2 ☐	PLM NY	PLM 600/M4/82/020 ☐	ABWA	TEM Wipe ASTM D-6480 ☐
		ABEPA2	NY ELAP 198.1 ☐	ABDMV	TEM Microvac ASTM D-5755 ☐
		ABENY	NY ELAP 198.6 PLM NOB ☐	Matrix	Other ☐
		ABBNY	NY ELAP 198.4 TEM NOB ☐		

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☒
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

Special Instructions						
Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop	
122-1EXT	↑ ↓					
2 EXT						
3 EXT						
4 EXT						
5 EXT						
6 EXT						

Relinquished by	Date	Time	Received by	Date	Time
			<u>CP</u>	SEP 09 2013	9:55 AM

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

Page ___ of ___

SanAir Technologies Laboratory

Analysis Report

prepared for

El Group, Inc Roanoke Office

Report Date: 9/11/2013
Project Name: City Of Staunton
Project #: IHRO130196
SanAir ID#: 13021163



Certification # 652931



License # LAB0166



804.897.1177

www.sanair.com



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

EI Group, Inc Roanoke Office
15 Salem Ave SE
Suite 301
Roanoke, VA 24011

September 11, 2013

SanAir ID # 13021163
Project Name: City Of Staunton
Project Number: IHRO130196

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 6 sample(s) were received on Tuesday, September 10, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 122-40, 122-41, 122-42, 122-43, 122-44, 122-45.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:
- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:
6 sample(s) in Good condition



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13021163

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHRO130196
P.O. Number:
Project Name: City Of Staunton

Collected Date: 9/9/2013
Received Date: 9/10/2013 9:30:00 AM
Report Date: 9/11/2013 10:20:32 AM
Analyst: Tallert, Jonathan G.

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-40 / 13021163-001	Black Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-41 / 13021163-002	Black Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-42 / 13021163-003	Black Non-Fibrous Homogeneous		95% Other	5% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-43 / 13021163-004 Roof Core	Black Non-Fibrous Heterogeneous	20% Cellulose	80% Other	None Detected
122-43 / 13021163-004 Gypsum	White Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-44 / 13021163-005	Brown Fibrous Homogeneous	70% Cellulose	30% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-45 / 13021163-006	Black Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Signature: 
Date: 9/11/2013

Reviewed: 
Date: 9/11/2013

Page 1 of 1

Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

SanAir ID Number

13021163

Bulk			Air			Soil/Vermiculite		
ABB	PLM EPA 600/R-93/116	☒	ABA	PCM NIOSH 7400	☐	ABSE	PLM EPA 600/R-93/116 (Qual.)	☐
	Positive Stop ☐		ABA-2	OSHA w/ TWA*	☐	ABSP	PLM CARB 435 (LOD <1%)	☐
ABEPA	PLM EPA 400 Point Count	☐	ABTEM	TEM AHERA	☐	ABSP1	PLM CARB 435 (LOD 0.25%)	☐
ABB1K	PLM EPA 1000 Point Count	☐	ABATN	TEM NIOSH 7402	☐	ABSP2	PLM CARB 435 (LOD 0.1%)	☐
ABBen	PLM EPA NOB	☐	ABT2	TEM Level II	☐			
ABBCH	TEM Chatfield	☐						
ABBTM	TEM EPA NOB	☐						
Water			New York ELAP			Dust		
			PLM NY	PLM 600/M4/82/020	☐	ABWA	TEM Wipe ASTM D-6480	☐
			ABEPA2	NY ELAP 198.1	☐	ABDMV	TEM Microvac ASTM D-5755	☐
			ABENY	NY ELAP 198.6 PLM NOB	☐	Matrix	Other	
ABHE	EPA 100.2	☐	ABBNY	NY ELAP 198.4 TEM NOB	☐			☐
Turn Around Times		3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☒			
		2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐			

Special Instructions

[illegible]

Relinquished by	Date	Time	Received by	Date	Time
<i>[Signature]</i>	9/9/2013	17:00	<i>[Signature]</i>	SEP 10 2013	9:30 AM

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

SanAir Technologies Laboratory

Analysis Report

prepared for

El Group, Inc Roanoke Office

Report Date: 9/19/2013
Project Name: Western State
Hospital
Project #: IHR0130196
SanAir ID#: 13022166



804.897.1177

www.sanair.com



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

EI Group, Inc Roanoke Office
15 Salem Ave SE
Suite 301
Roanoke, VA 24011

September 19, 2013

SanAir ID # 13022166
Project Name: Western State Hospital
Project Number: IHR0130196

Dear Stephen Clark,

We at SanAir would like to thank you for the work you recently submitted. The 1 sample(s) were received on Thursday, September 19, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 122-46.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:
- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:
1 sample(s) in Good condition



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13022166

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHR0130196
P.O. Number: Bldg 122
Project Name: Western State Hospital

Collected Date: 9/18/2013
Received Date: 9/19/2013 10:10:00 AM
Report Date: 9/19/2013 1:22:06 PM
Analyst: Sobrino, Sandra

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
122-46 / 13022166-001 Tan Flooring	Tan Non-Fibrous Homogeneous		100% Other	None Detected
122-46 / 13022166-001 Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected
122-46 / 13022166-001 Grey Flooring	Grey Non-Fibrous Homogeneous		100% Other	None Detected
122-46 / 13022166-001 Mastic	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Signature: *Sandra Sobrino*
Date: 9/19/2013

Reviewed: *[Signature]*
Date: 9/19/2013

Page 1 of 1

Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

SanAir ID Number

Company: <u>Est Group, Inc.</u>	Project #: <u>JHR013C196</u>	Collect by: <u>Stephen Clark</u>
Address: <u>206 Walnut Hills Rd</u>	Project Name: <u>Western State Hospital</u>	Phone #:
City, St., Zip: <u>Staunton, VA</u>	Date Collected: <u>7/18/2013</u>	Fax #:
State of Collection: <u>VA</u> Account#:	P.O. Number: <u>Bldg 122</u>	Email:

Bulk			Air			Soil/Vermiculite		
ABB	PLM EPA 600/R-93/116	☒	ABA	PCM NIOSH 7400	☐	ABSE	PLM EPA 600/R-93/116 (Qual.)	☐
	Positive Stop	☐	ABA-2	OSHA w/ TWA*	☐	ABSP	PLM CARB 435 (LOD <1%)	☐
ABEPA	PLM EPA 400 Paint Count	☐	ABTEM	TEM AHERA	☐	ABSP1	PLM CARB 435 (LOD 0.25%)	☐
ABB1K	PLM EPA 1000 Paint Count	☐	ABATN	TEM NIOSH 7402	☐	ABSP2	PLM CARB 435 (LOD 0.1%)	☐
ABBEEN	PLM EPA NOB	☐	ABT2	TEM Level II	☐			
ABBCH	TEM Chatfield	☐						
ABBTM	TEM EPA NOB	☐						
Water			New York ELAP			Dust		
			PLM NY	PLM 600/M4/82/020	☐	ABWA	TEM Wipe ASTM D-6480	☐
			ABEPA2	NY ELAP 198.1	☐	ABDMV	TEM Microvac ASTM D-5756	☐
			ABENY	NY ELAP 198.6 PLM NOB	☐			
ABHE	EPA 100.2	☐	ABBNY	NY ELAP 198.4 TEM NOB	☐	Matrix	Other	

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☒	12 HR ☐	24 HR ☒
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

[illegible]

Relinquished by	Date	Time	Received by	Date	Time
<i>[Signature]</i>	9/18/2013	1700	<i>[Signature]</i>	SEP 19 2013	1010am

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.