



WESTERN STATE HOSPITAL HAZARDOUS MATERIALS SURVEY

LAB ANALYSIS BUILDING #119

SanAir Technologies Laboratory

Analysis Report

prepared for

El Group, Inc Roanoke Office

Report Date: 9/5/2013
Project Name: Western State
Hospital
Project #: IHR0130196.00
SanAir ID#: 13020579



804.897.1177

www.sanair.com



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

EI Group, Inc Roanoke Office
15 Salem Ave SE
Suite 301
Roanoke, VA 24011

September 5, 2013

SanAir ID # 13020579
Project Name: Western State Hospital
Project Number: IHR0130196.00

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 32 sample(s) were received on Thursday, September 05, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 119-1, 119-2, 119-3, 119-4, 119-5, 119-6, 119-7, 119-8, 119-9, 119-10, 119-11, 119-12, 119-13, 119-14, 119-15, 119-16, 119-17, 119-18, 119-19, 119-20, 119-21, 119-22, 119-23, 119-24, 119-25, 119-26, 119-27, 119-28, 119-29, 119-30, 119-31, 119-32.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:
- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:
32 sample(s) in Good condition



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020579

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHR0130196.00
P.O. Number:
Project Name: Western State Hospital

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:03:32 PM
Analyst: Vaughan, Nathaniel

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
119-1 / 13020579-001 Cove Base	Beige Non-Fibrous Heterogeneous		100% Other		None Detected
119-1 / 13020579-001 Mastic	Yellow Non-Fibrous Heterogeneous		100% Other		None Detected
119-2 / 13020579-002 Cove Base	Beige Non-Fibrous Heterogeneous		100% Other		None Detected
119-2 / 13020579-002 Mastic	Yellow Non-Fibrous Heterogeneous		100% Other		None Detected
119-3 / 13020579-003 Cove Base	Black Non-Fibrous Heterogeneous		100% Other		None Detected
119-3 / 13020579-003 Mastic	Yellow Non-Fibrous Heterogeneous		100% Other		None Detected
119-4 / 13020579-004 Cove Base	Black Non-Fibrous Heterogeneous		100% Other		None Detected
119-4 / 13020579-004 Mastic	Yellow Non-Fibrous Heterogeneous		100% Other		None Detected
119-5 / 13020579-005	Yellow Non-Fibrous Heterogeneous		100% Other		None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 1 of 6



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020579

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHR0130196.00
P.O. Number:
Project Name: Western State Hospital

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:03:32 PM
Analyst: Vaughan, Nathaniel

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-6 / 13020579-006	Yellow Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-7 / 13020579-007	Black Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-8 / 13020579-008	Black Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-9 / 13020579-009 Floor Tile	Tan Non-Fibrous Heterogeneous		97% Other	3% Chrysotile
119-9 / 13020579-009 Mastic	Black Non-Fibrous Heterogeneous		97% Other	3% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-10 / 13020579-010 Floor Tile	Tan Non-Fibrous Heterogeneous		97% Other	3% Chrysotile
119-10 / 13020579-010 Mastic	Black Non-Fibrous Heterogeneous		97% Other	3% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-11 / 13020579-011 Drywall	White Non-Fibrous Heterogeneous	5% Cellulose	95% Other	None Detected
119-11 / 13020579-011 Joint Compound	White Non-Fibrous Heterogeneous		100% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 2 of 6



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020579

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHR0130196.00
P.O. Number:
Project Name: Western State Hospital

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:03:32 PM
Analyst: Vaughan, Nathaniel

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-12 / 13020579-012 Drywall	White Non-Fibrous Heterogeneous	5% Cellulose	95% Other	None Detected
119-12 / 13020579-012 Joint Compound	White Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-13 / 13020579-013 Drywall	White Non-Fibrous Heterogeneous	5% Cellulose	95% Other	None Detected
119-13 / 13020579-013 Joint Compound	White Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-14 / 13020579-014 Drywall	White Non-Fibrous Heterogeneous	5% Cellulose	95% Other	None Detected
119-14 / 13020579-014 Joint Compound	White Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-15 / 13020579-015 Floor Tile	Beige Non-Fibrous Heterogeneous		100% Other	None Detected
119-15 / 13020579-015 Mastic	Black Non-Fibrous Heterogeneous		97% Other	3% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-16 / 13020579-016 Floor Tile	Beige Non-Fibrous Heterogeneous		100% Other	None Detected
119-16 / 13020579-016 Mastic	Black Non-Fibrous Heterogeneous		97% Other	3% Chrysotile

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 3 of 6



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020579

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHR0130196.00
P.O. Number:
Project Name: Western State Hospital
Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:03:32 PM
Analyst: Vaughan, Nathaniel

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-17 / 13020579-017	Grey Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-18 / 13020579-018	Grey Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-19 / 13020579-019	White Fibrous Heterogeneous	55% Cellulose 25% Glass 10% Min. Wool	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-20 / 13020579-020	White Fibrous Heterogeneous	55% Cellulose 20% Glass 10% Min. Wool	15% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-21 / 13020579-021	White Fibrous Heterogeneous	55% Cellulose 25% Glass 10% Min. Wool	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-22 / 13020579-022	White Fibrous Heterogeneous	55% Cellulose 25% Glass 10% Min. Wool	10% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-23 / 13020579-023 Cove Base	Brown Non-Fibrous Heterogeneous		100% Other	None Detected
119-23 / 13020579-023 Mastic	White Non-Fibrous Heterogeneous		100% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 4 of 6



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020579

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHR0130196.00
P.O. Number:
Project Name: Western State Hospital

Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:03:32 PM
Analyst: Vaughan, Nathaniel

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-24 / 13020579-024 Cove Base	Black Non-Fibrous Heterogeneous		100% Other	None Detected
119-24 / 13020579-024 Mastic	White Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-25 / 13020579-025	Grey Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-26 / 13020579-026	Grey Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-27 / 13020579-027	Grey Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-28 / 13020579-028	Grey Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components	Asbestos Fibers
			% Non-Fibrous	
119-29 / 13020579-029	Grey Non-Fibrous Heterogeneous		100% Other	None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 5 of 6



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13020579

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHR0130196.00
P.O. Number:
Project Name: Western State Hospital
Collected Date: 9/4/2013
Received Date: 9/5/2013 10:15:00 AM
Report Date: 9/5/2013 4:03:32 PM
Analyst: Vaughan, Nathaniel

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
119-30 / 13020579-030	Grey Non-Fibrous Heterogeneous		100% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
119-31 / 13020579-031	White Non-Fibrous Heterogeneous		100% Other		None Detected

SanAir ID / Description	Stereoscopic Appearance	% Fibrous	Components		Asbestos Fibers
			% Non-Fibrous		
119-32 / 13020579-032	White Non-Fibrous Heterogeneous		100% Other		None Detected

Certification

Signature: 
Date: 9/5/2013

Reviewed: 
Date: 9/5/2013

Page 6 of 6

Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

Asbestos Chain of Custody

SanAir ID Number

13020579

Company: <u>The El Group Staunton</u>		Project #: <u>140013019600</u>		Collect by:
Address: <u>Mhart@ei1.com</u>		Project Name: <u>Western State Hospital</u>		Phone #:
City, St., Zip:		Date Collected: <u>9-4-13</u>		Fax #:
State of Collection: <u>VA</u> Account#:		P.O. Number:		Email:

Bulk		Air		Soil/Vermiculite	
ABB	PLM EPA 600/R-93/116	ABA	PCM NIOSH 7400	ABSE	PLM EPA 600/R-93/116 (Qual.)
	Positive Stop ☐	ABA-2	OSHA w/ TWA*	ABSP	PLM CARB 435 (LOD <1%)
ABEPA	PLM EPA 400 Point Count	ABTEM	TEM AHERA	ABSP1	PLM CARB 435 (LOD 0.25%)
ABBTK	PLM EPA 1000 Point Count	ABATN	TEM NIOSH 7402	ABSP2	PLM CARB 435 (LOD 0.1%)
ABBEN	PLM EPA NOB	ABT2	TEM Level II		
ABBCH	TEM Chatfield				
ABBTM	TEM EPA NOB				
Water		New York ELAP		Dust	
ABHE	EPA 100.2	PLM NY	PLM 600/M4/82/020	ABWA	TEM Wipe ASTM D-6480
		ABEPA2	NY ELAP 198.1	ABDMV	TEM Microvac ASTM D-5755
		ABENY	NY ELAP 198.6 PLM NOB		
		ABBNY	NY ELAP 198.4 TEM NOB		
				Matrix	Other

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☒
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

Special Instructions Send results to mhart@ei1.com

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
119-01					
↓					
119-82					

Relinquished by	Date	Time	Received by	Date	Time
			<u>J. A. Brown</u>	<u>9/5/13</u>	<u>10:15 AM</u>

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

Page ___ of ___

SanAir Technologies Laboratory

Analysis Report

prepared for

El Group, Inc Roanoke Office

Report Date: 9/11/2013
Project Name: Western State
Hospital
Project #: IHRO130196.00
SanAir ID#: 13021158



804.897.1177

www.sanair.com



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

EI Group, Inc Roanoke Office
15 Salem Ave SE
Suite 301
Roanoke, VA 24011

September 11, 2013

SanAir ID # 13021158
Project Name: Western State Hospital
Project Number: IHRO130196.00

Dear Melissa Hart,

We at SanAir would like to thank you for the work you recently submitted. The 2 sample(s) were received on Tuesday, September 10, 2013 via FedEx. The final report(s) is enclosed for the following sample(s): 119-33, 119-34.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino
Asbestos & Materials Laboratory Manager
SanAir Technologies Laboratory

Final Report Includes:
- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:
2 sample(s) in Good condition



SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070
Web: <http://www.sanair.com> E-mail: iaq@sanair.com

SanAir ID Number

13021158

FINAL REPORT

Name: El Group, Inc Roanoke Office
Address: 15 Salem Ave SE
Suite 301
Roanoke, VA 24011

Project Number: IHRO130196.00
P.O. Number:
Project Name: Western State Hospital

Collected Date: 9/9/2013
Received Date: 9/10/2013 9:30:00 AM
Report Date: 9/11/2013 1:48:41 PM
Analyst: Sobrino, Sandra

Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-33 / 13021158-001	Black Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
119-34 / 13021158-002 Built Up Roofing	Black Non-Fibrous Heterogeneous		100% Other	None Detected
119-34 / 13021158-002 Foam Insulation	Yellow Non-Fibrous Homogeneous		100% Other	None Detected

Certification

Signature: *Sandra Sobrino*
Date: 9/11/2013

Reviewed: *[Signature]*
Date: 9/11/2013

Page 1 of 1

Disclaimer

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983

SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B - Powhatan, VA 23139
804-897-1177 / 888-895-1177 / Fax 804-897-0070
www.sanair.com

Asbestos Chain of Custody

SanAir ID Number

13021158

Company: <u>The El Group Staunton</u>	Project #: <u>1180130196.00</u>	Collect by:
Address:	Project Name: <u>Western State Hospital</u>	Phone #:
City, St., Zip:	Date Collected: <u>9-9-13</u>	Fax #:
State of Collection: <u>VA</u> Account#:	P.O. Number:	Email:

Bulk			Air			Soil/Vermiculite		
ABB	PLM EPA 600/R-93/116	☒	ABA	PCM NIOSH 7400	☐	ABSE	PLM EPA 600/R-93/116 (Qual.)	☐
	Positive Stop	☐	ABA-2	OSHA w/ TWA*	☐	ABSP	PLM CARB 435 (LOD <1%)	☐
ABEPA	PLM EPA 400 Point Count	☐	ABTEM	TEM AHERA	☐	ABSP1	PLM CARB 435 (LOD 0.25%)	☐
ABB1K	PLM EPA 1000 Point Count	☐	ABATN	TEM NIOSH 7402	☐	ABSP2	PLM CARB 435 (LOD 0.1%)	☐
ABBEN	PLM EPA NOB	☐	ABT2	TEM Level II	☐			
ABBCH	TEM Chatfield	☐						
ABBTM	TEM EPA NOB	☐						
Water			New York ELAP			Dust		
ABHE	EPA 100.2	☐	PLM NY	PLM 600/M4/82/020	☐	ABWA	TEM Wipe ASTM D-6480	☐
			ABEPA2	NY ELAP 198.1	☐	ABDMV	TEM Microvac ASTM D-5755	☐
			ABENY	NY ELAP 198.6 PLM NOB	☐	Matrix	Other	
			ABBNY	NY ELAP 198.4 TEM NOB	☐			☐

Turn Around Times	3 HR (4 HR TEM) ☐	6 HR (8HR TEM) ☐	12 HR ☐	24 HR ☒
	2 Days ☐	3 Days ☐	4 Days ☐	5 Days ☐

Special Instructions Email results to mhart@ei1.com

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
119-33					
119-34					

Relinquished by	Date	Time	Received by	Date	Time
<u>[Signature]</u>	<u>9-9-13</u>	<u>1534</u>	<u>[Signature]</u>	<u>SEP 10 2013</u>	<u>9:30 AM</u>

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed To Recipient will be charged a \$10 shipping fee.

Page ___ of ___